

Field-mountable Fiber Optical Connector (FMC)

Operation Manual

(Type: TC-2, apply to 2*3 Bow-type drop fiber cable)

① Components and tools



1. Components



2. Auxiliary tools



3. Recommended Installation tools

② Assembly steps

Process the fiber




1.1 Put the cable into the boot



1.2 Strip the cable strengthen layer




1.3 Press the cable into the clamp



1.4 check the fiber




1.5 Clean the fiber



1.6 Put the cable into the cutting clamp




1.7 Cut the fiber



1.8 The fiber length specification


Assembly



2.1 Check the locker



2.2 Insert the fiber




2.3 Lock the boot




2.4 Lock the fiber(Take off the switch)

Disassembly




3.1 Assemble the auxiliary jig



3.2 Unlock the fiber



3.3 Unlock the boot



3.4 Pull out the fiber