



Field-mountable Fiber Optical Connector (FMC)

Operation Manual
(Type: TC-1, apply to 2*3 Bow-type drop fiber cable)


① Components and tools



1. Components




2. Auxiliary tools




3. Recommended Installation tools

② Assembly steps


Process the fiber




1.1 Strip the cable strengthen layer




1.2 Press the cable into the clamp




1.3 Strip the cable coating layer





1.4 check the fiber



1.5 Clean the fiber




1.6 Cut the fiber




1.7 The fiber length specification


Assembly




2.1 Check the locker



2.2 Insert the fiber




2.3 Complete the fiber insertion




2.4 Lock the fiber


Disassembly




3.1 Assemble the auxiliary jig



3.2 Unlock the fiber



3.3 Use the exclusive convex to open the cover



3.4 Pull out the fiber